

Part-1
Performa for the safety of School Building
(To be filled by the head of School/Institute)

- | | | |
|--|--|--|
| 1. Name of School | <u>Guru Hargobind Sr. Sec. Public School</u> | |
| 2. Location | <u>Sidhwan Khurd (Ludhiana)</u> | |
| 3. Plot Area | <u>2,44,516 Sq. Ft.</u> | |
| 4. Plinth Area | <u>96027 Sq. Ft.</u> | |
| 5. Number of Story | <u>Two (2)</u> | |
| 6. Year of construction of building | <u>Part-I in 1979, II- 1980, III- 1985, IV- 1990, V- 1993-95, VI-2010-13, VII- 2013-15</u> | |
| 7. Supervision of the qualified Engineer | | |
| The following details may be given: | | |
| a) Name of the Engineer | <u>S. Baljit Singh (Contractor, Builder)</u> | |
| b) Address | <u>VPO Sidhwan Khurd (Ludhiana)</u> | |
| c) Set of drawing used in construction | | |
| If available | <u>N.A.</u> | |
| d) Name of Architect | <u>N.A.</u> | |
| 8. Whether the building has been constructed for the purpose of: | | |
| a) School (Yes/No) | <u>Yes</u> | |
| b) Residential purpose and converted | | |
| For use as school (Yes/No) | <u>No</u> | |
| 9. Material used for Roof: | | |
| a) R.C.C Slabs (Yes/No) | <u>Yes</u> | |
| b) R.S. Joists and Battens (Yes/No) | <u>No</u> | |
| c) Wooden joists and Battens (Yes/No) | <u>No</u> | |
| 10. Material used for Walls: | | |
| a) Mud Mortar (Yes/No) | <u>No</u> | |
| b) Cement Mortar (Yes/No) | <u>Yes</u> | |
| c) Plaster a) Lime Mortar | <u>No</u> | |
| b) Cement Mortar (Yes/No) | <u>Yes</u> | |
| 11. Flooring: | | |
| a) Conglomerate (Yes/No) | <u>Yes</u> | |
| b) Terrazzo (Yes/No) | <u>No</u> | |
| c) Brick Paving (Yes/No) | <u>No</u> | |
| 12. Detailed Drawing indicating dimensions | | |
| Of the rooms along with size and location | | |
| Of doors and windows | <u>Attached</u> | |


PRINCIPAL
 Guru Hargobind Sr. Sec. Public School
 Sidhwan Khurd, (Ludhiana)
 Aff. No. 1630031 School No. 20035

Part-2

(To be filled by S.D.E of P.W.D. B&R Department)

Name of School... Guru Hargobind Sr. Sec. Public School Sadhwan Khyrd

I have visited the above mentioned school on 08/06/2026 and have visually inspected it from

all angles of safety and I found it fit for normal use as school building.

In case any addition/alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of a technically specified Engineer and this certificate may be obtained after the completion of the work from the undersigned.

In case the building is affected by flood or if there is settlement of walls/foundations or caves of roof etc. immediately inspection of the undersigned be arranged or check the stability and safety of the building.

This building can be safely occupied for normal use up to Date 31.03.2027
(Indicate year upto which it can be used). for year 2026-27.

[Signature]
8/6/2026

[Signature]
Sub Divisional Engineer
Construction Sub Division
PWD (B&R) Jagraon at Ludhiana

ਪਿੱਠ ਅੰਕਣ ਨੰ: 155-156

ਮਿਤੀ: 08/06/2026

1. ਉਪਰੋਕਤ ਸਕੂਲ ਦਾ ਇਸ ਦਫ਼ਤਰ ਦੇ ਜੂਨੀਅਰ ਇੰਜੀਨੀਅਰ ਵੱਲੋਂ ਨਿਰੀਖਣ ਕੀਤਾ ਗਿਆ ਅਤੇ ਸਕੂਲ/ਸੰਸਥਾ ਦੀ ਬਿਲਡਿੰਗ ਸੇਫ਼ ਪਾਈ ਗਈ। ਇਸ ਲਈ ਸਾਲ 2026-27 ਦੌਰਾਨ ਮਿਤੀ 31.03.2027 ਤੱਕ ਦਾ ਸਕੂਲ ਬਿਲਡਿੰਗ ਸੇਫ਼ਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ।
2. ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਨੰ: 1, ਲੋ:ਨਿ:ਵਿ:, ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਲੁਧਿਆਣਾ ਨੂੰ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।

[Signature]
Sub Divisional Engineer
Construction Sub Division
PWD (B&R) Jagraon at Ludhiana